

# Inspection Photos

Operator: Hilcorp Energy  
API: 067-07647  
Date: 8/10/2021



Photo 1. View of the project area from the well pad entrance facing center.





Photo 2. View of the southern project area from the southeastern corner of the working area facing westward. Interim reclamation area extends beyond working area fence and comprises open areas surrounding the well pad. Approximately 150 flowering musk thistles observed.





Photo 3. View of sediment discharge point within the southern project area.





Photo 4. View of fencing debris in the eastern portion of the well pad.





Photo 5. View of the eastern project area from the southeastern corner facing northward.





Photo 6. View of the reference area comprised of ponderosa pine woodland with understory of gambel oak, Oregon grape, Junegrass, and squirreltail.