



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	<a href="#">Lease road entrance</a>		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	<a href="#">Livestock fencing</a>		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	<a href="#">Panel</a>		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	<a href="#">Livestock fencing</a>		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	<a href="#">Panel</a>		
Corrective Action:		Date:	

<b>Equipment:</b>		corrective date
Type: Bradenhead	# 1	

Comment:	Bradenhead valve is exposed at surface.			Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:	Separator is anchored.			Date:	
Corrective Action:				Date:	
Type: Flow Line	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:	Calibration card noted in prior FIR #697004096 has been updated. See attached photo.			Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment:	Automation array and ECD scrubber			Date:	
Corrective Action:				Date:	
Type: Emission Control Device	# 1				
Comment:	Pilot is on			Date:	
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:	Crude oil tank is anchored.			Date:	
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,

Comment:	Produced water tank is anchored.	
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 246741 Type: WELL API Number: 123-14538 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/23/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 13 Fluid Type: VAPOR

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 435350 Type: TANK API Number: - Status: AC Insp. Status: AO

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697004375	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5507370">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5507370</a>