

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/17/2021

Submitted Date:

08/17/2021

Document Number:

690008292

**FIELD INSPECTION FORM**

Loc ID 329151 Inspector Name: Carlile, Craig On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                            | Comment |
|--------------|-------|----------------------------------|---------|
|              |       | cogcc.inspections@crestonepr.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name           | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 249141      | WELL | PR     | 07/06/2009  | GW         | 123-16943 | ARISTOCRAT FEDERAL 44-4 | PR          |

**General Comment:**

*(This area is intentionally left blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

|                    |               |  |       |
|--------------------|---------------|--|-------|
|                    | Type WELLHEAD |  |       |
| Comment:           |               |  |       |
| Corrective Action: |               |  | Date: |

**Emergency Contact Number:**

|                    |  |  |             |
|--------------------|--|--|-------------|
| Comment:           |  |  |             |
| Corrective Action: |  |  | Date: _____ |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

|                    |               |  |       |
|--------------------|---------------|--|-------|
|                    | Type WELLHEAD |  |       |
| Comment:           |               |  |       |
| Corrective Action: |               |  | Date: |

**Equipment:**

|                    |     |  |                 |
|--------------------|-----|--|-----------------|
|                    |     |  | corrective date |
| Type: Plunger Lift | # 1 |  |                 |
| Comment:           |     |  |                 |
| Corrective Action: |     |  | Date:           |

**Tanks and Berms:**

| Contents           | #  | Capacity | Type                | Tank ID | SE GPS |
|--------------------|--|----------|---------------------|---------|--------|
|                    |  |          | CENTRALIZED BATTERY |         | ,      |
| Comment:           | Battery services location number: 311323 |          |                     |         |        |
| Corrective Action: |  |          |                     | Date:   |        |

**Paint**

|                  |  |  |  |  |  |
|------------------|--|--|--|--|--|
| Condition        |  |  |  |  |  |
| Other (Content)  |  |  |  |  |  |
| Other (Capacity) |  |  |  |  |  |
| Other (Type)     |  |  |  |  |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |



**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment                                      | User     | Date       |
|--|----------|------------|
| <a href="#">Routine wellhead inspection.</a> | carlilec | 08/17/2021 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 690008293    | Photo       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5508298">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5508298</a> |