

Inspection Photos
Location Name: Champlin 86 Amoco F#4
Location ID: 319002



Photo 1 loc pic facing south

Photo 2 loc pic facing east.

Inspection Photos
Location Name: Champlin 86 Amoco F#4
Location ID: 319002



Photo 3 loc pic facing North



Photo 4 loc pic facing West

Inspection Photos
Location Name: Champlin 86 Amoco F#4
Location ID: 319002



Photo 5 Unused equipment and electrical piping.