

Inspection Photos
Location Name: Champlin 86 Amoco F# 7
Location ID: 323149



Photo 1 loc pic Weeds on site



Photo 2 Unused equipment PU and associated equipment.

Inspection Photos
Location Name: Champlin 86 Amoco F# 7
Location ID: 323149



Photo 3 Trash: black tarp



Photo 4 Stained soil and mechanical issue 2" piping to separator.

Inspection Photos
Location Name: Champlin 86 Amoco F# 7
Location ID: 323149



Photo 5 Loc pic



Photo 6 unused equipment: 1" piping and parts around Hoz Separator.