Inspector Name: Revas, Robbie

FORM INSP Rev X/20	1120 Linco Pho	Gas oln Stre ne: (30	ate of Col Conserva eet, Suite 801, D 3) 894-2100 Fa: INSPECTI	<b>tion C</b> enver, Co x: (303) 8	<b>ommi</b> blorado 80 94-2109				08 Submitt 08 Docume	on Date: 8/17/2021 ed Date: 8/17/2021 ent Number: 99304243
Loc ID 318912	Inspector Name: Revas, Robbie		On-Site Ii 2A	nspectior Doc Nur				I <mark>S Summary:</mark> HIS IS A FOLLOW UP IN	NSPECT	ION
Operator In	formation:							OLLOW UP INSPECTIO		
		6290					Findi			
Name of Op	erator: KP KAUFFMA	N CON	IPANY INC				10	-	3	
Address: 1	675 BROADWAY, STE	E 2800					1	Number of Corrective		
City:	DENVER St	tate:	CO	Zip:	8020	2	X C	 orrective Action Response R	Requested	t
							P	NY CORRECTIVE ACTI REVIOUS INSPECTION EEN ADDRESSED ARE	S THAT	HAVE NOT
Contact Inf								-		
Contact Na	ame	Phon	е	Email				Comment		
,				dnr_co .co.us	gccentor	cement@	state			
,				rwatzm	an@kpk	.com		All Inspections		
,				cogcc@	kpk.con	n		All Inspections		
Inspected F	Facilities:									
Facility ID				API Num				Insp Status		
242449 Conoral Co		TA	01/01/2020	OW		123-1024	40	LEONARD 24-21		TA
<u>General Co</u>	<u>mment:</u>									

Inspector Name: Revas, Robbie

			ļ	Location			
Lease Road:							
Туре	Access						
comment: location is in a pasture and has a 2 track access and is overgrown with weeds							
Corrective ActionL					Date		
Overall Good:							
Signs/Marker:							
Туре	WELLHEAD						
Comment:	adequate						
Corrective Action:					Date	:	
Emergency Contact I	Number:						
Comment:							
Corrective Action:	:				Date:		
Good Housekeeping	<u>g:</u>						
Туре	UNUSED EQUIPMENT						
Comment:	unused Pump Jack						
Corrective Action:	Comply with Rule 606				Date	: <u>08/13/2021</u>	
Overall Good:	I						
Spills:							
Туре	Area	Volume					
In Containment:	No						
Comment:							
Multilple Spills	and Releases?						
Fencing/:							
Туре	WELLHEAD						
Comment	Ag fence						
Corrective Action:			Date	:			
Equipment:	•					corrective date	
Type: Pump Jack	#	<b>#</b> 1					
Comment	: dissassembled and unu	ised					
Corrective Action	:				Date:		
Type: Bradenhead	#	¥ 1					
Comment	: appears to be plumbed	to surface					
Corrective Action	:				Date:		
Venting:							
Yes/No NO							
Comment:							
Corrective Action:					Date:		
Flaring:							

Туре		
Comment:		
Corrective Action:	Date:	

Inspector Name: Revas, Robbie

Facility ID:       242449       Type:       WELL       API Number:       123-10240       Status:       TA       Insp. Status:       TA         Purpose:       Shut In       Temporarily Abandoned       Reminder:			Inspected	d Facilities					
Purpose:       Shut In       Temporarily Abandoned       Reminder:         Comment:       TA	Facility ID: 242	449 Type: WELL	API Number:	123-10240	Status:	TA	Insp. Status:		
Purpose:       Shut In       Temporarily Abandoned       Reminder:         Comment:       TA			Idle \	Well					
Date:         BradenHead         Date:         BradenHead         Date:         One Fluid Type:         End Surf Csg Pressure:       0       Fluid Type:         Comment:         Corrective Action:       Date:         Corrective Action:       Date:         Corrective Action:       Date:         COGCC Comments         CodeCC Inspection Report Summary       Don Tuesday 8/17/2021 at approximately 1055 hrs. I, Inspector Robbie Revas,         Conducted an on-site inspection at a KP Kauffman location: This is a inspection to Doc # 509303810.       Any corrective actions from previous from previous anspections that have not been addressed are still applicable.         aeonard 24-21 at API #05-123-10240 in Weld County Colorado.         Mile there, I observed a wellste, TA at time of inspection.         Ouring this inspection the following possible compliance issues were observed and is now telinquint.         Sood colspane"2">Compliance issue have been addressed: S06 Housekeeping: runused pump jack equipment on location, CA date 8-13-2021. See thotos 3, 4 & 5.         Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.	Purpose:	Shut In 🔀 Temporari							
BradenHead         BradenHead         Date of Last Brhd Test: 10/13/2020         Annual Brhd Completed? Yes         Last Brhd Test Results         Initial Surf Csg Pressure: 0         End Surf Csg Pressure: 0         Comment:         Comment:         Corrective Action:         Coefficient Colspan="2">Date:         Coefficient Colspan="2">Coefficient Colspan="2">Date:         Coefficient Colspan="2"	Comme	ent: TA							
Date of Last Bihd Test:       10/13/2020       Annual Bihd Completed?       Yes         Last Bihd Test Results       Initial Surf Csg Pressure:       0       Fluid Type:         End Surf Csg Pressure:       0       Comment:       Date:         Corrective Action:       Date:       Date:         Corrective Action:       Date:       Corrective Action:       Date:         Corrective Action:       Vest       Date:       08/17/2021         Conducted an on-site inspection at a KP Kauffman location: This is a inspection to Doc #       revasr       08/17/2021         On Tuesday 8/17/2021 at approximately 1055 hrs. I, Inspector Robbie Revas,       Conducted an on-site inspection at a KP Kauffman location: This is a inspection to Doc #       revasr       08/17/2021         Ondright in spection the following possible compliance issues were observed and is now delinquint:       Soft Act at the of inspection.       Inspection the following possible compliance issues were observed and is now delinquint:       Soft Act at API #05-123-10240 in Weld County Colorado.       Inspection the following possible compliance issues have been cleaned up.       Soft Act at API #05-123-10240 in Weld County Colorado.         While there, I observed a wellsite, TA at time of inspection.       Count at a PI #05-123-10240 in Weld County Colorado.       Soft Act at API #05-123-10240 in Weld County Colorado.       Soft Act at API #05-123-10240 in Weld County Colorado.       Soft Act at API #05-123-10240 in Weld C									
Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0 Comment: Corrective Action: Date: Corrective Action: Date: Comment COGCC Comments COGCC Inspection Report Summary On Tuesday 8/17/2021 at approximately 1055 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: This is a inspection to Doc # Any corrective actions from previous nspections that have not been addressed are still applicable. e.eonard 24-21 at API #05-123.10240 in Weld County Colorado. Nurile there, I observed a wellsite, TA at time of inspection. During this inspection the following possible compliance issues were observed and is now telinquint: SoGe Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See shotos 3, 4 & 5. During this inspection the following possible compliance issue have been addressed: 506 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up. See attached photos. cocation: (fy, Weather: clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Attached Documents You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number: Document Num Description URL			Brade	nHead					
End Surf Csg Pressure:       0         Comment:       Date:         Corrective Action:       Date:         COCCC Comments         Comment:         COCCC Comments         COCCC Comments         Contractive Action:         Date:         COCCC Comments         COCCC Inspection Report Summary         On Tuesday 8/17/2021 at approximately 1055 hrs. I, Inspector Robbie Revas,         Conducted an on-site inspection at a KP Kauffman location: This is a inspection to Doc #         Boy 2018/10.         Any corrective actions from previous         inspections that have not been addressed are still applicable.         Leanard 24-21 at API #05-123-10240 in Weld County Colorado.         While there, I observed a wellsite, TA at time of inspection.       During this inspection the following possible compliance issues were observed and is now delinquint:         606 Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See photos.       See attached photos.         Location: dry, Weather: clear.       A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.         Attached Documents <td c<="" td=""><td>Date of Last Brhd</td><td>Test: 10/13/2020</td><td>Annual Brhd Co</td><td>mpleted? Yes</td><td></td><td></td><td></td></td>	<td>Date of Last Brhd</td> <td>Test: 10/13/2020</td> <td>Annual Brhd Co</td> <td>mpleted? Yes</td> <td></td> <td></td> <td></td>	Date of Last Brhd	Test: 10/13/2020	Annual Brhd Co	mpleted? Yes				
Comment:	Last Brhd Test Re	sults Initial Surf Csg Pressu	re: 0	Fluid Type:					
Corrective Action:       Date:         Corrective Action:       COGCC Comments         Comment       User       Date         COGCC Inspection Report Summary       On Tuesday 8/17/2021 at approximately 1055 hrs. I, Inspector Robbie Revas,       revasr       08/17/2021         Conducted an on-site inspection at a KP Kauffman location: This is a inspection to Doc #       Any corrective actions from previous       revasr       08/17/2021         Inspections that have not been addressed are still applicable.       Any corrective actions from previous       Inspection the following possible compliance issues were observed and is now delinquint:       Boot and the following possible compliance issue have been addressed:       Boot at the following possible compliance issue have been addressed:       Boot at the following possible compliance issue have been cleaned up.         See attached photos.       Location: dry, Weather: clear.       A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been cleaned up.       See attached photos.         Compliance issues have been corrected to comply with COGCC rules.       This is a summary of inspection report.       Image: State sta		End Surf Csg Pressure	e: 0						
COGCC Comments           Comment         User         Date           COGCC Inspection Report Summary         revasr         08/17/2021           On Tuesday 8/17/2021 at approximately 1055 hrs. I, Inspector Robbie Revas,         revasr         08/17/2021           Conducted an on-site inspection at a KP Kauffman location: This is a inspection to Doc #         g99303810.         revasr         08/17/2021           Leonard 24-21 at API #05-123-10240 in Weld County Colorado.         Multe there, I observed a wellsite, TA at time of inspection.         During this inspection the following possible compliance issues were observed and is now         delinquint:           0606 Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See photos 3, 4 & 5.         During this inspection the following possible compliance issue have been addressed:         606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up.           See attached photos.         Location: dry, Weather: clear.         A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.         This is a summary of inspection report.           Attached Documents         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:         Document Num	Comment	:							
Comment       User       Date         COGCC Inspection Report Summary On Tuesday 8/17/2021 at approximately 1055 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: This is a inspection to Doc # 699303810.       revasr       08/17/2021         Any corrective actions from previous inspections that have not been addressed are still applicable. Leonard 24-21 at API #05-123-10240 in Weld County Colorado.       Any corrective actions from previous inspection the following possible compliance issues were observed and is now delinquint: 606 Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See photos 3, 4 & 5.       See photos 3, 4 & 5.         During this inspection the following possible compliance issue have been addressed: 606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up. See attached photos. Location: dry, Weather: clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.       Attached Documents         Vou can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:         Document Num       Description       URL	Corrective Action	:					Date:		
Comment       User       Date         COGCC Inspection Report Summary On Tuesday 8/17/2021 at approximately 1055 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: This is a inspection to Doc # 699303810.       revasr       08/17/2021         Any corrective actions from previous inspections that have not been addressed are still applicable. Leonard 24-21 at API #05-123-10240 in Weld County Colorado.       Any corrective actions from previous inspection the following possible compliance issues were observed and is now delinquint: 606 Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See photos 3, 4 & 5.       See photos 3, 4 & 5.         During this inspection the following possible compliance issue have been addressed: 606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up. See attached photos. Location: dry, Weather: clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.       Attached Documents         Vou can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:         Document Num       Description       URL									
COGCC Inspection Report Summary       revasr       08/17/2021         On Tuesday 8/17/2021 at approximately 1055 hrs. I, Inspector Robbie Revas,       revasr       08/17/2021         Conducted an on-site inspection at a KP Kauffman location: This is a inspection to Doc #       599303810.       Any corrective actions from previous       and corrective actions from previous       an			<u>COGCC (</u>	<u>Comments</u>					
On Tuesday 8/17/2021 at approximately 1055 hrs. I, Inspector Robbie Revas,         Conducted an on-site inspection at a KP Kauffman location: This is a inspection to Doc #         699303810.       Any corrective actions from previous         inspections that have not been addressed are still applicable.         Leonard 24-21 at API #05-123-10240 in Weld County Colorado.         While there, I observed a wellsite, TA at time of inspection.         During this inspection the following possible compliance issues were observed and is now         delinquint:         606 Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See         photos 3, 4 & 5.         During this inspection the following possible compliance issue have been addressed:         606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up.         See attached photos.         Location: dry, Weather: clear.         A follow up on this site inspection needs to be conducted to ensure the         Compliance issues have been corrected to comply with COGCC rules.         This is a summary of inspection report.         Attached Documents         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:         Document Num       Description						User			
Conducted an on-site inspection at a KP Kauffman location: This is a inspection to Doc #         699303810.       Any corrective actions from previous         inspections that have not been addressed are still applicable.       Leonard 24-21 at API #05-123-10240 in Weld County Colorado.         While there, I observed a wellsite, TA at time of inspection.       During this inspection the following possible compliance issues were observed and is now delinquint:         606 Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See photos 3, 4 & 5.       During this inspection the following possible compliance issue have been addressed:         606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up.       See attached photos.         Location: dry, Weather: clear.       A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.         This is a summary of inspection report.       Attached Documents         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:       Document Num         Description       URL			55 bre 1 Inepactor	Pobbio Povas		revasr	08/17/2021		
699303810.       Any corrective actions from previous         inspections that have not been addressed are still applicable.       Leonard 24-21 at API #05-123-10240 in Weld County Colorado.         While there, I observed a wellsite, TA at time of inspection.       During this inspection the following possible compliance issues were observed and is now delinquint:         606 Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See photos 3, 4 & 5.       During this inspection the following possible compliance issue have been addressed:         606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up.       See attached photos.         Location: dry, Weather: clear.       A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.         This is a summary of inspection report.       Attached Documents         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:       Decument Num         Document Num       URL					n to Doc #				
Leonard 24-21 at API #05-123-10240 in Weld County Colorado. While there, I observed a wellsite, TA at time of inspection. During this inspection the following possible compliance issues were observed and is now delinquint: 606 Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See photos 3, 4 & 5. During this inspection the following possible compliance issue have been addressed: 606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up. See attached photos. Location: dry, Weather: clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Attached Documents You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number: Document Num Description URL									
While there, I observed a wellsite, TA at time of inspection.         During this inspection the following possible compliance issues were observed and is now delinquint:         606 Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See photos 3, 4 & 5.         During this inspection the following possible compliance issue have been addressed:         606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up.         See attached photos.         Location: dry, Weather: clear.         A follow up on this site inspection needs to be conducted to ensure the         Compliance issues have been corrected to comply with COGCC rules.         This is a summary of inspection report.         Attached Documents         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:         Document Num       Description									
During this inspection the following possible compliance issues were observed and is now         606 Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See         photos 3, 4 & 5.         During this inspection the following possible compliance issue have been addressed:         606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up.         See attached photos.         Location: dry, Weather: clear.         A follow up on this site inspection needs to be conducted to ensure the         Compliance issues have been corrected to comply with COGCC rules.         This is a summary of inspection report.         Attached Documents         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:         Document Num       Description				).					
delinquint:         606 Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See         photos 3, 4 & 5.         During this inspection the following possible compliance issue have been addressed:         606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up.         See attached photos.         Location: dry, Weather: clear.         A follow up on this site inspection needs to be conducted to ensure the         Compliance issues have been corrected to comply with COGCC rules.         This is a summary of inspection report.         Attached Documents         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:         Document Num       Description				ware cheer od					
606 Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See         photos 3, 4 & 5.         During this inspection the following possible compliance issue have been addressed:         606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up.         See attached photos.         Location: dry, Weather: clear.         A follow up on this site inspection needs to be conducted to ensure the         Compliance issues have been corrected to comply with COGCC rules.         This is a summary of inspection report.         Attached Documents         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:         Document Num       Description		cuon the following possible	compliance issues	were observed	and is now				
photos 3, 4 & 5.         During this inspection the following possible compliance issue have been addressed:         606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up.         See attached photos.         Location: dry, Weather: clear.         A follow up on this site inspection needs to be conducted to ensure the         Compliance issues have been corrected to comply with COGCC rules.         This is a summary of inspection report.         Attached Documents         You can go to COGCC Images ( <a href="https://cogcc.state.co.us/weblink/">https://cogcc.state.co.us/weblink/</a> ) and search by document number:         Document Num       Description         URL		na: unused pump iack equir	oment on location.	CA date 8-13-20	021. See				
606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up.         See attached photos.         Location: dry, Weather: clear.         A follow up on this site inspection needs to be conducted to ensure the         Compliance issues have been corrected to comply with COGCC rules.         This is a summary of inspection report.         Attached Documents         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:         Document Num       Description			,						
See attached photos.       Location: dry, Weather: clear.         A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.         This is a summary of inspection report.         Attached Documents         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:         Document Num       Description         URL									
Location: dry, Weather: clear.         A follow up on this site inspection needs to be conducted to ensure the         Compliance issues have been corrected to comply with COGCC rules.         This is a summary of inspection report.         Attached Documents         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:         Document Num       Description         URL			around WH appear	to have been c	cleaned up.				
A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.       Image: Compliance issues have been corrected to comply with COGCC rules.         Attached Documents       Image: Compliance issues (https://cogcc.state.co.us/weblink/) and search by document number:         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:       Image: Compliance issues (https://cogcc.state.co.us/weblink/)         Document Num       Description       Image: Compliance issues (https://cogcc.state.co.us/weblink/)									
This is a summary of inspection report.         Attached Documents         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:         Document Num       Description         URL	A follow up on th	is site inspection needs to b	be conducted to en	sure the					
Attached Documents         You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:         Document Num       Description         URL			comply with COGC	C rules.					
You can go to COGCC Images ( <u>https://cogcc.state.co.us/weblink/</u> ) and search by document number: Document Num Description URL	This is a summa	ry of inspection report.							
Document Num Description URL	Attached Docur	ments_							
	You can go to C	OGCC Images ( <u>https://cogc</u>	c.state.co.us/weblir	<u>nk/</u> ) and search	by document	number:			
699304244 location pics http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5508692		Description							
	699304244	location pics	http://ogccweblink.s	state.co.us/Downlo	oadDocumentP	DF.aspx?l	DocumentId=5508692		