

Inspection Photos

API: 071-07085

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/16/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07085 | Date: 8/16/2021

Inspection Photos



Photo 1. Facing south toward the access road stream crossing which was washed out during the flood event.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 8/16/2021

Inspection Photos



Photo 2. There are two culverts installed at the stream crossing. This appears to be inadequate as the prior cement culvert shown in the photo on the right had 3 large outlets.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 8/16/2021

Inspection Photos



Photo 3. Facing northwest at the stream crossing. There is no bank stabilization at the outlet side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 8/16/2021

Inspection Photos



Photo 4. Facing southeast along the access road. Gravel was being hauled to the road during inspection. All disturbed areas will need to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 8/16/2021

Inspection Photos



Photo 5. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 8/16/2021