

# Inspection Photos

API: 071-07604

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/16/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07604 | Date: 8/16/2021

## Inspection Photos



**Photo 1.** Facing east toward the access road stream crossing which was washed out during the flood event.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07604 | Date: 8/16/2021

## Inspection Photos



**Photo 2.** There are multiple culverts installed and rock rip/rap was installed for bank stabilization. The culverts are multiple sizes and it is unknown if this was an adequate engineered practice.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07604 | Date: 8/16/2021

## Inspection Photos



**Photo 3.** Facing east at the stream crossing. There is bank stabilization along the outlet side of the stream crossing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07604 | Date: 8/16/2021

## Inspection Photos



**Photo 4.** Facing southeast along the access road. The culverts along the access road are filled in with sediment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07604 | Date: 8/16/2021

## Inspection Photos



**Photo 5.** The culverts along the access road are filled in with sediment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07604 | Date: 8/16/2021

## Inspection Photos



**Photo 6.** Facing back down the road. There is erosion along the road side and stormwater is bypassing culverts which will cause further erosion. BMP's need to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07604 | Date: 8/16/2021

## Inspection Photos



**Photo 7.** Another culvert further along the road is filled in with sediment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07604 | Date: 8/16/2021

## Inspection Photos



**Photo 8.** Facing southeast toward the well site.

