

Inspection Photos

API: 071-08095

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/16/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08095 | Date: 8/16/2021

Inspection Photos



Photo 1. Facing east at the drainage crossing. This area was damage in the flood event where exposed pipe lines were observed. This area has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08095 | Date: 8/16/2021

Inspection Photos



Photo 2. Further along the road at this drainage, the culvert plugged up and stormwater had flown over the road. The culvert needs to be repaired at this drainage area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08095 | Date: 8/16/2021

Inspection Photos



Photo 3. The same culvert outlet has eroded and exposed a pipeline. This area needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08095 | Date: 8/16/2021

Inspection Photos



Photo 4. Facing west toward the well site. There is erosion across the access road which needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08095 | Date: 8/16/2021

Inspection Photos



Photo 5. Facing toward the well and PW pit. The water level is near 2 ft. freeboard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08095 | Date: 8/16/2021