

Inspection Photos

API: 071-08098

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/16/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08098 | Date: 8/16/2021

Inspection Photos



Photo 1. There is stormwater erosion occurring down the road. The road needs to be repaired and stormwater diverted off the road and toward culverts.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08098 | Date: 8/16/2021

Inspection Photos



Photo 2. There are culverts along the road that have filled in with sediment and need maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08098 | Date: 8/16/2021

Inspection Photos



Photo 3. There is stormwater erosion occurring down the road. The road needs to be repaired and stormwater diverted off the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08098 | Date: 8/16/2021

Inspection Photos



Photo 4. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08098 | Date: 8/16/2021