

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/16/2021

Submitted Date:

08/18/2021

Document Number:

690201985

FIELD INSPECTION FORM

Loc ID 308487 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272827	WELL	PR	09/22/2004	GW	071-08113	CHATEAU 34-14	RI

General Comment:

[This is a stormwater management inspection.](#)
[See attached photos and additional details within this report.](#)

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is a culvert along the main road that is partially washed out and is also filled in with debris. There is erosion along the side of the road which has exposed a flowline. There is erosion along the access road with insufficient BMP's causing stormwater to flow down a long stretch of the road side. Areas of erosion need to be repaired.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C Date: 09/30/2021

Pits: NO SURFACE INDICATION OF PIT

Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective _____ Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment: _____

Corrective _____ Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective _____ Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: NO

Comment: The water level was near 2 ft. freeboard.

Corrective Lower fluid level so at least two feet of freeboard exists per Rule 909.c. Date: 08/20/2021

Permit:	Facility ID	Permit Num	Expiration Date
	278519	1445868	
	278519	1445868	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402785215	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5509735
690201986	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5509683