

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2021

Submitted Date:

08/12/2021

Document Number:

696203033

**FIELD INSPECTION FORM**Loc ID 335669 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10668

Name of Operator: CAERUS ENERGY SERVICES LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arauza, Steven		steven.arauza@state.co.us	
,		COGCC.inspections@caerus oilandgas.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335669	LOCATION	AC			-	STORY GULCH UNIT- 64S96W 26SEW	RI

**General Comment:**

On 8/10/2021, Reclamation Specialist Trujillo inspected Caerus Piceance LLC's Story Gulch Unit 64S96W 26SEW location in Garfield County, Colorado.

This inspection is a followup to #696202980 to document compliance with the following corrective action:  
606.o.(3): Compromised liner

It was observed that the liner at the tank battery remains compromised.

Refer to the "Location" Sections of this inspection report for additional details.

Any corrective action(s) from previous inspections that have not been addressed are still applicable; refer to inspection ##696202980 for CAs regarding stormwater.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal		Walls Insufficient		Inadequate
Comment:	<p>Previous inspection observed that the secondary containment liner at the tank battery was compromised; liner pulled from wall on the west end of the containment; hole in liner on the south end of the containment.</p> <p>It was observed that the liner has been repaired on the west end of the containment; however, hole on the south end of the liner has not been repaired.</p> <p>CA remains applicable.</p>			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 08/30/2021

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 335669 Type: LOCATION API Number: - Status: AC Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402778392	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5504623">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5504623</a>
696203034	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5504608">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5504608</a>