

**Inspection Photos
UPRR 42 Pan Am F #4
Spill ID 480343 (AC)**



Photo 1 – Spill excavation is open. Impacts remain in-situ.



Photo 2 – Spill excavation is open. Impacts remain in-situ. Seepage of groundwater was observed in the lowest point on the floor/sidewall of the excavation.

Inspection Photos
UPRR 42 Pan Am F #4
Spill ID 480343 (AC)



Photo 3 – Spill excavation is open. Impacts remain in-situ.



Photo 4 – Small amount of soil staining remains on surface. Fencing up around open excavation.