

Inspection Photos

Operator: Arkoma/Catamount
API: 067-10021
Date: 8/12/2021



Photo 1. View of the project area from the well pad entrance facing southward.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing, largely with crested wheatgrass, smooth brome, and western wheatgrass.



Photo 3. View of erosional channel forming within the flowline ROW, approximately 1 foot wide and deep, needs stabilization.



Photo 4. View of stormwater BMPs within the southeastern project area straw bales and wattles need maintenance and reinforcement.



Photo 5. View of the reference area comprised pinyon and juniper woodland with understory of gambel oak, sagebrush, antelope bitterbrush, and squirreltail.