

# Inspection Photos

Operator: Arkoma/Catamount  
API: 067-05294  
Date: 8/12/2021



Photo 1. View of the project area from the well pad entrance facing northward.



Photo 2. View of the northern project area from the northwestern corner facing eastward.





Photo 3. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with smooth brome, western wheatgrass, and rubber rabbitbrush.





Photo 4. View of area along the access road where improperly diverged flows have eroded the road surface and hillside (facing upslope). Gravel is washed downslope approximately 50 feet.





Photo 5. View of area where stormwater flows have washed out the road surface, depositing fill and gravel down-slope.





Photo 6. View of another area on the access showing where gravel and fill material is discharging from the access road.





Photo 7. View of the reference area comprised pinyon and juniper woodland with understory of gambel oak, sagebrush, antelope bitterbrush, and squirreltail.