

Inspection Photos

Operator: Arkoma/Catamount
API: 067-10018
Date: 8/12/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Visible vegetation is comprised of kochia. Little to no desirable vegetation observed.



Photo 3. Aerial view of vegetation within the interim reclamation area, comprised of dense kochia weeds.



Photo 4. View of debris washed down from above the project area, within the southern diversion.



Photo 5. View of area along the well pad cut-slope with rilling and debris deposition, facing southward.



Photo 6. Another view of area on the well pad cut-slope with significant rilling and channeling (up to 1 foot wide and deep).



Photo 7. View of rilling, exposed roots, and sediment deposition at the toe of the cut-slope.



Photo 8. View of eroded BMP within the northwestern project area where cobble and wattles are washed out.



Photo 9. View of sediment deposition observed below failed BMP in Photo 8.



Photo 10. View of the reference area comprised pinyon and juniper woodland with understory of gambel oak, sagebrush, antelope bitterbrush, and squirreltail.