

Inspection Photos
Operator: Merrion
API: 067-09173
Date: 8/17/2021



Photo 1. View of calf stuck within facilities area.



Photo 2. View of inadequate fencing around the separator where it appears calf got into facility area. It appears additional panels are needed here.



Photo 3. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with grasses similar to those observed in the reference area, such as smooth brome, orchard grass, tall fescue, and perennial ryegrass.



Photo 4. View of the reference area comprised of irrigated crop fields, comprised of grasses and forbs typically used in irrigated grass fields within the region.