

Inspection Photos

API: 071-08082

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/16/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08082 | Date: 8/16/2021

Inspection Photos



Photo 1. Facing east toward the access road stream crossing which was washed out during the flood event. The road side area shown at red arrow is beginning to erode and needs to be stabilized.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08082 | Date: 8/16/2021

Inspection Photos



Photo 2. Facing back west at the stream crossing. There are two additional culverts installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 8/16/2021

Inspection Photos



Photo 3. Facing southwest toward the access road. Stormwater further up the road is directed toward this area. There are insufficient BMP's along the road side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 8/16/2021

Inspection Photos



Photo 4. Facing back down the road. The erosion along the road side will need to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 8/16/2021

Inspection Photos



Photo 5. Further up the access road. The erosion along the road side will need to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 8/16/2021

Inspection Photos



Photo 6. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 8/16/2021