

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/11/2021

Submitted Date:

08/23/2021

Document Number:

700300252**FIELD INSPECTION FORM**Loc ID 306783 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264756	WELL	PR	09/17/2002	GW	067-08752	JAMES COLE B 2	PR

General Comment:

Complaint response inspection and sound survey. Complaint #402770006 for noise at 382 Cole Ranch rd. See complaint section and uploaded sound reports.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	loose flowline segment by wellhead		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Flow Line	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	wellhead		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment:					

Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 264756	Type: WELL	API Number: 067-08752	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing. Freeflowing well with large compressor. Note: if well is being produced under vacuum conditions, approval would be needed.

Corrective Action:

Date:

Complaint

Comment: Complaint #402770006 for noise experienced at residence south of well pad. A 3M SoundProDL meter was used calibrated before and after survey. A link to sound survey reports is at end of report. Low frequency measurements were taken at residence first, 25' from exterior wall and 5 feet from ground. The 19 minute survey averaged 61.6 db(c).

At the equipment, readings were taken at edge of pad due to topography dropping off in direction of residence. Sound levels were then calculated to the 350' equivalent. 61.2 db (a) @ 69' = 47 db(a) @ 350'

Note: the muffler is pointed on the side of equipment that faces residence, re configuring muffler and sound panels could make improvements to the low frequency noise experienced by complainant.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300260	a-scale survey at equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5511825
700300261	c-scale syurvey at residence	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5511826
700300262	muffler and sound wall orientation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5511827
700300263	sound meter placement at edge of pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5511828
700300264	sound meter placement 25' from house	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5511829