

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2021

Submitted Date:

08/24/2021

Document Number:

700900629**FIELD INSPECTION FORM**Loc ID 319894 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #225City: AURORA State: CO Zip: 80016**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201799	WELL	PR	08/17/1977	GW	001-07203	MUEGGE HAND 41-31 1	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

1

Comment: Appears to be plumbed to the surface

Corrective Action:

Date:

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition

Other (Content)

Other (Capacity) 75 bbls

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shares berm with crude tank						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		39.839250,-104.584206	
Comment: Stained soil on back side of tank						
Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Corrective Action Date 9/17/2021 to remove stained soil. See attached photo #6						Date: 09/27/2021
Paint						
Condition	Inadequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate		
Comment: Inadequate berms around tank(s)						
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4). Corrective Action Date 9/17/2021. See attached photo # 1 & 5.						Date: 09/27/2021
Wells Served By Facilities Above				AirsID		
API Number		API Number		AirsID		
001-07203						
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						
Date:						
Flaring:						
Type						
Comment:						
Corrective Action:						
Date:						

Inspected FacilitiesFacility ID: 201799 Type: WELL API Number: 001-07203 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appears to be plumbed to surface

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday August 5, 2021 at approximately 12:35pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Muegge Hand 41 – 31 #1, Renegade oil & gas company at</p> <p>API # 001-07203 in Adams County Colorado.</p> <p>While there, I observed a shut in well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Corrective Action Date 9/17/2021 to remove stained soil. See attached photo #6</p> <p>Visual Impact Mitigation. Paint tanks per Rule 804. 90 days if no seasonal issues. Corrective Action Date 9/17/2021. See attached photos #1 & 5.</p> <p>Inadequate berms around tank(s) Repair or install berms or other secondary containment devices per Rule 605.a.(4). Corrective Action Date 9/17/2021. See attached photo # 1 & 5.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	08/24/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900630	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513853