

Inspection Photos

API: 025-06022

Operator: GRAND MESA OPERATING CO

Inspection Date: 8/23/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 025-06022 | Date: 8/23/2021

Inspection Photos



Photo 1. Facing southeast at the drainage crossing located at Lat/Long:38.343699,-103.638603. The drainage crossing has eroded and is impassible with vehicle. This needs to be repaired and designed to allow access across this drainage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06022 | Date: 8/23/2021

Inspection Photos



Photo 2. Facing northwest at the drainage crossing that eroded shown in previous photo. This drainage crossing needs to be repaired per good engineering practice.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 025-06022 | Date: 8/23/2021

Inspection Photos



Photo 3. Facing southwest toward the access road which had been reclaimed. The desirable vegetation has failed to establish and will need to be reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06022 | Date: 8/23/2021

Inspection Photos



Photo 4. View of vegetation along the access road shows mostly bare soil and weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06022 | Date: 8/23/2021

Inspection Photos



Photo 5. Facing southwest toward the location which is fenced.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06022 | Date: 8/23/2021

Inspection Photos



Photo 6. Center of the location facing south. The location has not established desirable vegetation and consists mostly of undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06022 | Date: 8/23/2021

Inspection Photos



Photo 7. Center of the location facing east. The



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06022 | Date: 8/23/2021

Inspection Photos



Photo 8. Center of the location facing north.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06022 | Date: 8/23/2021

Inspection Photos



Photo 9. Center of the location facing west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06022 | Date: 8/23/2021

Inspection Photos



Photo 10. View of ground cover shows undesirable vegetation growth; Kochia, Russian thistle. Desirable vegetation has not established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06022 | Date: 8/23/2021

Inspection Photos



Photo 11. Facing southeast showing the undisturbed area on the left and the disturbance of the location on the right.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06022 | Date: 8/23/2021