

Inspection Photos  
Operator: Simcoe  
API: 067-09679  
Date: 8/12/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward.





Photo 3. View of erosion occurring at culvert outlet along access road, indicating that this culvert is not adequate to support flows in this drainage. An area approximately 3ft x 8ft volume of material is eroded around the culvert, as well as scouring and transport of road materials.





Photo 4. View of gravel, road, material and scoured soils downstream from area where stormwater event flowed over the access road. Sediment discharge in this area is approximately 25 feet long and 4 feet wide, depth unknown.





Photo 5. View of scouring and erosion on soils down-slope from the access road.





Photo 6. View of culvert inlet on upstream side of access crossing. Significant erosion is not observed upstream from access road crossing.





Photo 7. View of the reference area comprised of pinyon and juniper woodland with black sage, prickly pear, penstemon, squirreltail, and James galleta.