

Inspection Photos
Operator: Simcoe
API: 067-05796
Date: 8/12/2021



Photo 1. View of the southern portion of the working area from the western edge facing center. Stormwater flows over the well pad largely appear contained by a silt trap along the western edge. Monitoring and maintenance will be needed to maintain site stabilization due to site layout.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Reinforced berms and silt trap are installed.



Photo 3. View of silt trap observed within the northern project area.



Photo 4. View of hay mulch on berm and germination observed.



Photo 5. View of the reference area comprised sagebrush shrubland with James galleta, squirreltail, penstemon, and snakeweed.