

Inspection Photos

Operator: Hilcorp Energy
API: 067-06664
Date: 8/17/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area facing eastward. Vegetation is progressing within the interim reclamation areas, with irrigated grasses such as smooth brome.



Photo 3. View of the eastern project area facing southward. Reference area in background is comprised of irrigated crop grasses.