

Inspection Photos
Operator: Merrion
API: 067-09209
Date: 8/17/2021



Photo 1. View of the project area from the well pad entrance facing center.




Photo 2. View of risers and unused equipment within the project area.



Photo 3. View of the southern project area facing eastward. Revgetation is progressing on fill slopes, largely with rubber rabbitbrush. Kochia weeds need to be managed to prevent debris. Unused equipment also present here.



Photo 4. View of the eastern project area facing southward.



Photo 5. View of gravel and sediment discharged from overflow of stormwater downstream from the access road (area approx. 15ft wide x 25ft long)



Photo 6. View of the reference area comprised of a mosaic of wetland (cattails and rushes), as well as greasewood, sagebrush, and rabbitbrush shrubland.