

Inspection Photos
Location Name: Longmont Farms Unit 5
API 05-123-13222, Spill 479267, REM 18932



Photo 1: Longmont Farms Unit 5 well sign



Inspection Photos
Location Name: Longmont Farms Unit 5
API 05-123-13222, Spill 479267, REM 18932



Photo 2: Excavation from southeast corner, looking northwest. Flowline exposed in northwest corner of excavation – highlighted by red circle.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Longmont Farms Unit 5
API 05-123-13222, Spill 479267, REM 18932



Photo 3: Excavation from southeast corner, looking west. Flowline exposed in south wall of excavation.



Inspection Photos
Location Name: Longmont Farms Unit 5
API 05-123-13222, Spill 479267, REM 18932



Photo 4: Excavation from southeast corner. Erosion of excavation wall in southeast corner.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Longmont Farms Unit 5
API 05-123-13222, Spill 479267, REM 18932



Photo 5: Excavation looking at southeast corner. Erosion of excavation wall in southeast corner.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Longmont Farms Unit 5
API 05-123-13222, Spill 479267, REM 18932



Photo 6: Excavation from southwest corner. Erosion is occurring in foreground, and in southeast corner in upper right of photo.



Inspection Photos

Location Name: Longmont Farms Unit 5
API 05-123-13222, Spill 479267, REM 18932



Photo 7: Excavation from northwest corner looking east. Fencing is a combination of cattle panels, snow fence and caution tape.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Longmont Farms Unit 5
API 05-123-13222, Spill 479267, REM 18932



Photo 8: Northwest corner of excavation looking along north wall. Flowline is exposed in northwest corner of excavation (highlighted by red circle).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Longmont Farms Unit 5
API 05-123-13222, Spill 479267, REM 18932



Photo 9: Northwest corner of excavation looking along southeast. Erosion of southeast corner visible.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Longmont Farms Unit 5
API 05-123-13222, Spill 479267, REM 18932



Photo 10: Material stockpile east of excavation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Longmont Farms Unit 5
API 05-123-13222, Spill 479267, REM 18932



Photo 11: Overview of excavation from east, looking west.

