

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2021

Submitted Date:

08/27/2021

Document Number:

693700858

**FIELD INSPECTION FORM**

Loc ID 323578 Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Inspections, KPK		cogcc@kpk.com	<a href="#">All KPK Inspections</a>
MacLaren, Joe		joe.maclaren@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245427	WELL	SI	04/01/2021	OW	123-13222	LONGMONT FARMS UNIT 5	EI
479267	SPILL OR RELEASE	CL	07/19/2021		-	Longmont Farms Unit #5 Flowline	EI

**General Comment:**

**Inspected Facilities**

Facility ID: 245427 Type: WELL API Number: 123-13222 Status: SI Insp. Status: EI

Facility ID: 479267 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: No Operator personnel or equipment onsite at time of inspection. A fiberglass flowline is exposed in northwest corner of excavation. Fence is now composed of a combination of cattle panel and snow fence. Fencing currently appears to be intact but may be quickly undermined with the collapse of an excavation wall. Fence is along edge of excavation walls and south wall of excavation is experiencing erosion from stormwater. Additional storm events pose a hazard of collapsing the excavation wall and undermining the fence. Stockpile east of excavation has earthen berm.

Operator has submitted a Form 27, Document #402777901, REM 18932 in review by COGCC. Operator has not supplied the information required on a Form 19 as specified in the previous inspection: "Operator also to submit Form 19 Supplemental Report with root cause and corrective action for flowline failure. Operator to submit results of flowline repair pressure test on Form 19 Supplemental Report.

Corrective Action: Operator to identify fiberglass line and contact COGCC Engineering Integrity Group for Abandonment or repair pursuant to Rules 1102 and 1105. Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700859	Longmont Farms Unit 5	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5517946">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5517946</a>