


# Inspection Photos

Operator: Western Gas Resources  
API: 067-06178  
Date: 8/26/2021



Photo 1. View of area where eastern riser (1 of 2 risers) was removed, southeast of well pad and access road, facing northward.





Photos 2/3. View of spotted knapweeds observed within the project area. Approximately 30 individuals observed, and less than 10 yellow toadflax.





Photo 4. View of portion of the southwestern cut-slope that remains unstabilized and lacking revegetation.





Photo 5. Closeup view of portion of cut-slope that remains unstabilized. BMP is degraded and rilling is occurring on the slope.





Photo 6. View of wattles in the southern project area, that are full of sediment and need stabilization. Additional seeding is needed here for long-term stabilization.