

Inspection Photos
Operator: Williford
API: 067-05446
Date: 8/25/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of spotted knapweed observed on the eastern fill lope drainage. Approximately 200 individuals observed.



Photo 3. View of dense weedy vegetation (kochia and Russian thistle) growing in the tank battery berm and containment.