

# Inspection Photos

API: 071-06902

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/27/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest along the main road to the well site. There is erosion along the road which is causing sediment accumulation at the culvert and at the main road in Lorencito Canyon.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 8/27/2021

## Inspection Photos



**Photo 2.** Facing northeast along the main road to the well site. There are noxious weeds (Diffuse knapweed) along the road that needs to be controlled. Some of the noxious weeds are beginning to disperse seed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 8/27/2021

## Inspection Photos



**Photo 3.** Facing northeast along the access road to the well site. There are noxious weeds (Diffuse knapweed) along the road that needs to be controlled. Some of the noxious weeds are beginning to disperse seed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 8/27/2021

## Inspection Photos



**Photo 4.** Facing northeast toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 8/27/2021