

**Inspection Photos**  
**Location Name: HLADKY O'GORMAN #3**  
**Location ID: 332971**



**Photo 1 loc pic**



**Photo 2 loc pic**

**Inspection Photos**  
**Location Name: HLADKY O'GORMAN #3**  
**Location ID: 332971**



**Photo 3 WH sign**



**Photo 4 loc pic**

**Inspection Photos**  
**Location Name: HLADKY O'GORMAN #3**  
**Location ID: 332971**



**Photo 5 Hoz separator**



**Photo 6 TNK BTRY**

**Inspection Photos**  
**Location Name: HLADKY O'GORMAN #3**  
**Location ID: 332971**



**Photo 7 breach in secondary containment berm.**



**Photo 8 Sediment from breach in containment berm carrying sediment off location into field.**

**Inspection Photos**  
**Location Name: HLADKY O'GORMAN #3**  
**Location ID: 332971**



**Photo 9 Breach in secondary containment berm.**



**Photo 10 Meter run**

**Inspection Photos**  
**Location Name: HLADKY O'GORMAN #3**  
**Location ID: 332971**



Colorado Oil and Gas Conservation Commission  
40.1214, -104.78959, 1487.0m  
Aug 23, 2021 13:19:31

**Photo 11 flow rate on meter run.**



Colorado Oil and Gas Conservation Commission  
40.12143, -104.78966, 1483.0m  
Aug 23, 2021 13:18:53

**Photo 12 loc pic.**