

Inspection Photos
Operator: Hubbs III
API: 067-07171
Date: 8/26/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of weeds growing around well, needing management.



Photo 3. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing similar to surrounding field with rubber rabbitbrush, Indian ricegrass, and weeds such as cheatgrass.



Photo 4. View of the eastern project area from the southeastern corner facing northward.



Photo 5. View of reference area comprised of open grass and shrub field with rubber rabbitbrush, Indian ricegrass, and weeds such as portulaca and cheatgrass.