

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2021

Submitted Date:

08/30/2021

Document Number:

693700860**FIELD INSPECTION FORM**Loc ID 326976 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 88380Name of Operator: TINDALL OPERATING COMPANYAddress: P.O. BOX 4507City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		clwitzel@hotmail.com	
		dnroilgas@hotmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111633	PIT	AC			-	NICKERSON 4	EI

General Comment:

COGCC followup to Remediation 18534

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	#		corrective date
Comment:	flowline riser present at pit.		
Corrective Action:	Abandon flowline pursuant to Rule 1105.		Date: 10/31/2021

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental

Spill/Remediation:

Comment: Remediation 18534 followup inspection. Remediation Project 18534 approved for pit investigation and closure. Operator indicated work would be complete by 8/30/2021, but work apparently has not commenced.

Corrective Action: Submit a Form 27 Supplemental with project update and timeline for completion of work.

Date: 09/15/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Lined: Pit ID: 111633 Lat: 40.576696 Long: -103.916270

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment: Corrective Action Date: **Fencing:**

Fencing Type: Fencing Condition:

Comment: Corrective Action Date: **Netting:**

Netting Type: Netting Condition:

Comment: Corrective Action Date:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment: Pit remains on location - see Remediation section of Inspection reportCorrective Action Date: **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700861	Produced water pit looking southeast	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519237