FORM INSP Rev X/20		d Gas Lincoln Stro Phone: (30	tate of Co Conserva eet, Suite 801, E 03) 894-2100 Fa DINSPECT	Denver, Color Denver, Color Denx: (303) 894-	rado 802 -2109				<u>C</u> Submit <u>C</u> Docum	tion Date: 08/19/2021 ted Date: 08/19/2021 tent Number: 099503105
Loc ID Inspector Name: On-Site Inspection 320083 MEDINA, JUSTIN 2A Doc Num: Operator Information: OGCC Operator Number: 10711 Name of Operator: PAINTED PEGASUS PETROLEUM LLC Address: 16820 BARKER SPRINGS RD #521 City: HOUSTON State: TX Zip: 77084							Status Summary: THIS IS A FOLLOW UP INSPECTION FOLLOW UP INSPECTION REQUIRED NO FOLLOW UP INSPECTION REQUIRED Findings: 5 Number of Comments 1 Number of Corrective Actions Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE			
Contact In Contact N		Phor	ne	Email jh@p3pet jm@p3pe				Comment		
Inspected Facility ID 202563 General Co	Type WELL	Status	Status Date 06/01/2020	Well C	lass	API Num 001-079		Facility Name UPRR 60 PAN AM E	2	Insp Status SI

			L	<u>ocation</u>						
Overall Good: 🔀										
Emergency Contact N	lumber:									
Comment:										
Corrective Action:	rrective Action:									
Good Housekeeping	<u></u>									
Туре	WEEDS									
Comment:	weeds unmanaged on loo									
Corrective Action:	Date:	07/10/2020								
Overall Good:					1					
<u>Spills:</u>										
Туре	Area	Volume								
In Containment: N	10									
Comment:										
Multilple Spills a	and Releases?									
Fencing/:										
Туре	WELLHEAD									
Comment:	chain link with barb wire									
Corrective Action:					Date:					
Equipment:	•					corrective date				
Type: Gas Meter Run	#	1								
Comment:										
Corrective Action:					Date:					
Type: Bradenhead	#	1								
Comment:										
Corrective Action:					Date:					
Type: Bird Protectors	#	2								
Comment:										
Corrective Action:					Date:					
Type: Emission Conti	ol Device #	1								
Comment:										
Corrective Action:					Date:					
Type: Horizontal Hea	ted Separator #	1								
Comment:										
Corrective Action:					Date:					
Type: Plunger Lift	#	1								
Comment:										
Corrective Action:					Date:					
Type: Ancillary equip	ment #	1								

I		,										
Commer	nt: <mark>aut</mark>	omati	on	1								
Corrective Actio	n:								Date:			
Tanks and Berms:											,	
Contents			#	Capacity		Туре		Tank ID	SE GPS	E GPS		
CRUDE OIL 1 300 BBLS STEEL AST ,												
Comm	ent:											
Corrective Action:							Date	:				
Paint												
Condition Adequate												
Other (Content)												
Other (Capacity)												
Other (Type)												
<u>Berms</u>												
Туре	Capa	city			Perr	meability (Wall)	Permeability	(Base)	Maintenance			
Earth	Adeq	Adequate			Walls Sufficent Base Suffic			ent	Adequate			
Comment:	Comment:											
Corrective Action:	on:							Date	:			
Contents # Capacity			Туре			Tank ID	SE GPS					
PRODUCED WATER 1 100 BBL				S	Open Top		,					
Comment:												
Corrective Action:						Date	Date:					
<u>Paint</u>												
Condition Adeq	uate											
Other (Content)												
Other (Capacity)												
Other (Type)												
<u>Berms</u>					-						_	
Туре	Capa	city			Perr	meability (Wall)	Permeability	(Base)	Maintenance			
Earth	Adeq	uate			Wal	Is Sufficent	Base Sufficient		Adequate	Adequate		
Comment:												
Corrective Action:									Date	:		
<u>Venting:</u>												
Yes/No NO												
Comment:												
Corrective Action:							Date:					
<u>Flaring:</u>												
Туре												
Commen	_									_		
Corrective Action:							Date:					

Inspected Facilities											
Facility ID: 202	563 Type: _	WELL	API Number:	001-07968	Status:	SI	Insp	. Status:	SI		
Idle Well											
Purpose: 🔀 Shut In Temporarily Abandoned Reminder:											
Comme	ent: SI										
Corrective Acti	Date	Date:									
			Brade	enHead							
Date of Last Brhd Test: 05/06/2020 Annual Brhd Completed? Yes											
Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:											
	End Surf C	Sg Pressure:	0								
Comment	:										
Corrective Action	:						Date:				
			00000	Comments							
Comment				<u>comments</u>		User		Date			
	ion Report Summ					medina	.	08/19/202	21		
On 8/19/21 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- UPRR 60 MAN AM E2 Company Name- P3 API- 05-001-07968 In Adams County Colorado. While there, I observed SI well This is a follow up inspection from document # 700900204 Corrective Actions are Delinquent. During this inspection the following possible compliance issues were observed: Weeds unmanaged on location Comply with COGCC housekeeping rules. 7/10/20 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. Other corrective actions have been addressed. This is a summary of inspection report.											
Attached Docur	OGCC Images (<u>h</u>	ttps://coacc.s	state.co.us/webli	nk/) and search	bv document	numbei					
Document Num			JRL	,							
402790183											
699503106	699503106 inspection pictures <u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513523</u>										
699503106	inspection pictur	es <u>h</u>	ttp://ogccweblink.s	state.co.us/Downl	oadDocumentF	<u>'DF.aspx</u>	?Docume	entId=55135	23		