

Inspection Photos
Location Name: Dungan 32-5 #5-4
API: 05-007-06222



Dungan 32-5 #5-4 pump jack and well head.



Erosional channel forming along eastern edge of location.

Inspection Photos
Location Name: Dungan 32-5 #5-4
API: 05-007-06222



Wattles along eastern edge of location require maintenance.



Sediment deposited on location from cut slope on southern edge of location.