

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/25/2021

Submitted Date:

09/01/2021

Document Number:

688800969

FIELD INSPECTION FORMLoc ID 419311 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900

City: HOUSTON State: TX Zip: 77002

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		sjninspections@ikavenergy.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419311	LOCATION	AC			-	PERINO WATER TRANSFER	EI
480299	SPILL OR RELEASE	AC	07/21/2021		-	Perino Water Transfer	EI

General Comment:

On August 25, 2021 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Simcoe LLC Produced Water Transfer System Spill/Release Point ID #480299. For the most recent field inspection report of this facility, please refer to document #688800031.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Western tank label is illegible.			
Corrective Action:	Comply with Rule 605.h.			Date: 09/22/2021
Type	OTHER			
Comment:	Location sign posted near locked gate at access road entrance off of CR 977. Previous operator listed on location signs.			
Corrective Action:	Comply with Rule 605.a.			Date: 09/22/2021
Type	BATTERY			
Comment:	Tank battery sign posted near pump house. Previous operator listed on signage.			
Corrective Action:	Comply with Rule 605.e.			Date: 09/22/2021
Emergency Contact Number:				
Comment:	Posted on location signs.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds noted during previous inspection have been mowed.			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	OTHER			
Comment:	Stock panel fencing around pump house.			
Corrective Action:				Date:
Equipment:				
Type: Bird Protectors	# 2			corrective date
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:				

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	HEATED STEEL AST		37.015001,-107.449429	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Concrete	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>419311</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>480299</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

Environmental**Spills/Releases:**Type of Spill: PRODUCED WATEREstimated Spill Volume: 35

Comment: Please refer to Spill/Release Point ID #480299 for more information regarding this release. During this inspection the impacted area had a pool of water present. This fluid must be treated like E&P waste and be removed promptly. Safety fencing is in disrepair and livestock have access to the area.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.Date: 09/02/2021Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
<p>On August 25, 2021 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Simcoe LLC Produced Water Transfer System Spill/Release Point ID #480299. For the most recent field inspection report of this facility, please refer to document #688800031.</p> <p>Please refer to Spill/Release Point ID #480299 for more information regarding this release. During this inspection the impacted area had a pool of water present. This fluid must be treated like E&P waste and be removed promptly. Safety fencing is in disrepair and livestock have access to the area.</p> <p>Corrective actions noted on this inspection document have been carried over from previous inspection. Simcoe has contacted the COGCC regarding facility closure plans. Replacing signage at a facility that is pending closure is not required at this point. Corrective actions pertaining to signage will be addressed by the Operator via an FIRR.</p>	hughesjo	09/01/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800970	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5521607