

Inspection Photos
Operator: Kinder Morgan
API: 083-06473
Date: 8/31/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with antelope bitterbrush, rubber rabbitbrush, Indian ricegrass, western wheatgrass, and crested wheatgrass.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of rig cable in the southern project area near the well pad entrance.



Photo 5. View of reference area comprised of pinyon and juniper woodland with serviceberry, Indian ricegrass, Eaton's penstemon, and gambel oaks.