

**Inspection Photos**  
**Location Name: Champlin 248 Amoco A3**  
**Location ID: 320030**



**Photo #1 tanks.**




**Photo #2 Separator.**

**Inspection Photos**  
**Location Name: Champlin 248 Amoco A3**  
**Location ID: 320030**



**Photo #3 Pump Jack.**



**Photo #4 unmaintained berm on east side of tanks.**



**Inspection Photos**  
**Location Name: Champlin 248 Amoco A3**  
**Location ID: 320030**



**Photo #5 stained soil on the back side of tank to the south.**



**Photo #6 Stained soil on back side of middle tank.**