

Inspection Photos
Location Name: Gladys #2
API: 05-067-09363



Gladys #2 location photo.



Herbicide stored on pump jack skid.

Inspection Photos
Location Name: Gladys #2
API: 05-067-09363



Well head and surrounding soil are stained with oil.



Gladys #1 and #2 tank battery.

Inspection Photos
Location Name: Gladys #2
API: 05-067-09363



Stained soil beneath truck load out valve.



Truck load out valve on horizontal tank is wet and stained with oil. Soil beneath valve is wet and stained.