

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2021

Submitted Date:

09/01/2021

Document Number:

688800973**FIELD INSPECTION FORM**Loc ID 306948 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 7125Name of Operator: BEEMAN OIL & GAS LLCAddress: 3401 QUEBEC ST SUITE 9105City: DENVER State: CO Zip: 80207**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Lawton, Lisa		lisa@beemanoil.com	
Beeman, Bob		robertbeeman@msn.com	Owner
Galloway, Kelly		kgallowaywerc@gmail.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282621	WELL	PR	08/01/2020	OW	067-09099	GLADYS 1	EI
479272	OFF- LOCATION FLOWLINE	AC	01/28/2021		-	Dump Line 14NENE	EI

General Comment:

On August 26, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Beeman Oil and Gas LLC Gladys #1. For the most recent field inspection report of this facility, please refer to document #693903586. The COGCC regional Reclamation Specialist was on site during this site visit.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign posted near well head.			
Corrective Action:				Date:
Type	BATTERY			
Comment:	Sign posted at shared tank battery.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location signs.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Crude Oil	Tank	<= 1 bbl		
Comment:	See corrective actions on Inspection Document #688800971 regarding stained soil at shared tank battery.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 10/01/2021
Crude Oil	WELLHEAD	<= 1 bbl		
Comment:	Stained soil near well head.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 10/01/2021
In Containment: No				
Comment:				
<input checked="" type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	IGNITOR/COMBUSTOR			
Comment:	Combustor and electrical supply panel have fencing.			
Corrective Action:				Date:
Equipment:				
Type: Prime Mover	# 1			corrective date
Comment:	Electric motor.			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Combustor			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical supply panel.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		37.109286,-108.110425
Comment:	Gladys #1 and #2 shared tank battery facility ID #479276.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	252
Other (Type)	Horizontal skid mounted.

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		37.109286,-108.110425
Comment:	Gladys #1 and #2 shared tank battery facility ID #479276.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	210
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Wells Served By Facilities Above

API Number
067-09099

AirsID

API Number	AirsID
------------	--------

067-09363

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 282621	Type: WELL	API Number: 067-09099	Status: PR	Insp. Status: EI
Facility ID: 479272	Type: OFF-	API Number: -	Status: AC	Insp. Status: EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On August 26, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Beeman Oil and Gas LLC Gladys #1. For the most recent field inspection report of this facility, please refer to document #693903586. The COGCC regional Reclamation Specialist was on site during this site visit. Inspection Document #688800971 lists corrective actions regarding stained soil at the shared tank battery. Stained soil was observed around the well head during this inspection.	hughesjo	09/01/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800974	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5521928