

Inspection Photos
Location Name: Gas Gathering Pipeline System
Spill/Release Point ID #480312



Area where fluids allegedly day lighted from Spill/Release Point ID #480312.



Pipeline markers near release point.

Inspection Photos
Location Name: Gas Gathering Pipeline System
Spill/Release Point ID #480312



Point source of Spill/Release Point ID #480312 on hillside adjacent to Highway 151.



Initial actions included scraping up impacted material from along flow path.

Inspection Photos
Location Name: Gas Gathering Pipeline System
Spill/Release Point ID #480312



Flow path continued along Highway 151.



Released fluids travelled beneath Highway 151.

Inspection Photos
Location Name: Gas Gathering Pipeline System
Spill/Release Point ID #480312



Impacted material on east side of Highway 151.



Flow path continued on east side of Highway through culvert beneath dirt road.

Inspection Photos
Location Name: Gas Gathering Pipeline System
Spill/Release Point ID #480312



Outlet of culvert beneath dirt road.



Area to the east of the dirt road. Culvert outfall is located on the left side of this picture.

Inspection Photos
Location Name: Gas Gathering Pipeline System
Spill/Release Point ID #480312



Impacted material in natural drainage.



Reported terminus of released fluids in drainage.