

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/01/2021

Submitted Date:

09/01/2021

Document Number:

679604136

**FIELD INSPECTION FORM**

Loc ID 441696 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

**Findings:**

- 37 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441686	WELL	PR	04/18/2017	OW	123-41458	Evans 10C-14-L	PR
441687	WELL	PR	12/01/2019	OW	123-41459	Evans 3N-14B-XR	PR
441688	WELL	PR	04/18/2017	OW	123-41460	Evans 4N-14A-XR	PR
441689	WELL	PR	01/01/2017	OW	123-41461	Evans 25N-14B-L	PR
441690	WELL	PR	03/01/2017	OW	123-41462	Evans 9N-14C-L	PR
441691	WELL	PR	12/01/2019	OW	123-41463	Evans 10N-14C-L	PR
441692	WELL	PR	01/01/2021	OW	123-41464	Evans 24C-14-L	PR
441693	WELL	PR	03/01/2017	OW	123-41465	Evans 24N-14B-L	PR
441694	WELL	PR	12/01/2020	OW	123-41466	Evans 29C-14-XR	PR
441695	WELL	PR	12/01/2019	OW	123-41467	Evans 24N-14A-L	PR
441697	WELL	PR	12/01/2019	OW	123-41468	Evans 4N-14C-XR	PR
441698	WELL	PR	06/01/2019	OW	123-41469	Evans 9C-14-L	PR
441699	WELL	PR	02/01/2017	OW	123-41470	Evans 29N-14C-XR	PR
441700	WELL	PR	07/01/2020	OW	123-41471	Evans 4N-14B-XR	PR
441701	WELL	PR	02/01/2017	OW	123-41472	Evans 10N-14A-L	PR
441702	WELL	PR	04/01/2017	OW	123-41473	Evans 25C-14-L	PR
441703	WELL	PR	01/01/2021	OW	123-41474	Evans 4C-14-XR	PR
441704	WELL	PR	02/01/2017	OW	123-41475	Evans 24N-14C-L	PR
441705	WELL	PR	02/01/2020	OW	123-41476	Evans 11N-14C-L	PR
441706	WELL	PR	04/01/2017	OW	123-41477	Evans 29N-14A-XR	PR
441707	WELL	PR	12/01/2019	OW	123-41478	Evans 10N-14B-L	PR
441708	WELL	PR	08/01/2020	OW	123-41479	Evans 30N-14B-XR	PR

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds at various wellheads. See attached photos.		
Corrective Action:	Remove to comply with Rule 606.	Date:	09/15/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused/disconnected equipment. See attached photos.		
Corrective Action:	Comply with Rule 606	Date:	09/15/2021
Type	OTHER		
Comment:	It appears to be stained soil at one wellhead. See attached photos.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d.	Date:	11/01/2021

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	6' chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	6' chain link		
Corrective Action:		Date:	

<b>Equipment:</b>		corrective date
Type: Horizontal Heated Separator	#	
Comment:	24 TOTAL	
Corrective Action:		Date:
Type: Compressor	# 1	
Comment:		
Corrective Action:		Date:
Type: Vertical Separator	# 2	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	#	
Comment:	22 TOTAL	
Corrective Action:		Date:
Type: Bird Protectors	#	
Comment:	24 TOTAL	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	#	
Comment:	22 TOTAL	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	STEEL AST		
Comment:	Tank appears to not be grounded. See attached photo.				
Corrective Action:	Design all equipment to prevent accumulation of static charge per Rule 608.d.				Date: 09/03/2021

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:		Shares containment with crude oil tanks.				
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	100 BBLs	BV CONCRETE		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	16	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		

Comment:		
Corrective Action:		Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	441686	Type:	WELL	API Number:	123-41458	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	441687	Type:	WELL	API Number:	123-41459	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	441688	Type:	WELL	API Number:	123-41460	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	441689	Type:	WELL	API Number:	123-41461	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	441690	Type:	WELL	API Number:	123-41462	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	441691	Type:	WELL	API Number:	123-41463	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	441692	Type:	WELL	API Number:	123-41464	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	441693	Type:	WELL	API Number:	123-41465	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				

Facility ID: 441694	Type: WELL	API Number: 123-41466	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
Facility ID: 441695	Type: WELL	API Number: 123-41467	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 441697	Type: WELL	API Number: 123-41468	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 441698	Type: WELL	API Number: 123-41469	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 441699	Type: WELL	API Number: 123-41470	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 441700	Type: WELL	API Number: 123-41471	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 441701	Type: WELL	API Number: 123-41472	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 441702	Type: WELL	API Number: 123-41473	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			
Corrective Action:			Date:	

Facility ID: 441703	Type: WELL	API Number: 123-41474	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:				Date:
Facility ID: 441704	Type: WELL	API Number: 123-41475	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:				Date:
Facility ID: 441705	Type: WELL	API Number: 123-41476	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:				Date:
Facility ID: 441706	Type: WELL	API Number: 123-41477	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:				Date:
Facility ID: 441707	Type: WELL	API Number: 123-41478	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:				Date:
Facility ID: 441708	Type: WELL	API Number: 123-41479	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      **Weather Conditions: cloudy, dry ground                      On Wednesday, September 1, 2021 at approximately 12:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at EVANS 7-26 PAD (PDC Energy), at location #: 441696 in WELD COUNTY Colorado.                      While there, I observed a producing facility.                      During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> <li>1. It appears that stained soil is at one wellhead. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d. (Corrective Action Date: November 1, 2021) See attached photos #4-6.</li> <li>2. Overgrown weeds at wellheads. Remove to comply with Rule 606. (Corrective Action Date: September 15, 2021) See attached photos 7-9.</li> <li>3. Tank connected to wellheads is appears blue to not be grounded. Design all equipment to prevent accumulation of static charge per Rule 608.d. (Corrective Action Date: September 3, 2021) See attached photo #10.</li> <li>4. Unused/disconnected equipment on various parts of location. Risers that are disconnected need to be LO/TO within 48 hours. If operator has no plans for future use, remove them per Rule 606. Remove all other equipment if not in use per Rule 606. (Corrective Action Date: November 1, 2021) See attached photos #11-16.</li> </ol> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	09/01/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679604137	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5522707">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5522707</a>