

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/25/2021

Submitted Date:

09/02/2021

Document Number:

688800978

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Hughes, Jim _____ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10663

Name of Operator: ENDURING RESOURCES LLC

Address: 1050 17TH STREET SUITE 2500

City: DENVER State: CO Zip: 80265

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Walter, Kyle		kwalter@enduringresources.com	All Inspections
Huntington, Heather		hhuntington@enduringresources.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216163	WELL	PR		GW	067-07769	BURNETT 2-1	EI
480579	SPILL OR RELEASE	AC	08/25/2021		-	BURNETT 2-1	EI

General Comment:

On August 25, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources Spill/Release Point ID #480579. For the most recent field inspection report for the Burnett #2-1, please refer to Document #693902647. A construction crew was on-site during this inspection.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	PBV is labeled with contents, capacity, and had NFPA placard.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Free standing sign near location entrance.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location sign.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Guard fencing present.			
Corrective Action:				Date:
Type	LOCATION			
Comment:	Perimeter fencing.			
Corrective Action:				Date:
Equipment:				
Type: Bird Protectors	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	Operating at the time of this inspection.			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:

Type: Ancillary equipment	# 2	
Comment:	Flowline risers.	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:	Marker by location entrance is down.	
Corrective Action:	Comply with Rule 603.j.	Date: 10/01/2021
Type: Prime Mover	# 1	
Comment:	Electric motor.	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.234566,-107.818492
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	PBV was point source of Spill/Release Point ID #480579. Released fluids breached secondary containment berm.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 10/01/2021

Wells Served By Facilities Above**AirsID**

API Number	API Number	AirsID
067-07769		

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>216163</u>	Type:	<u>WELL</u>	API Number:	<u>067-07769</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>480579</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

--

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 40

Comment: [Refer to Spill/Release Point ID #480579 in the COGIS database for more information regarding this release.](#)

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 10/01/2021

Reportable: YES

GPS: Lat 37.234562

Long -107.818498

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Drip pot on load out line.
Rip Rap	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On August 25, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources Spill/Release Point ID #480579. For the most recent field inspection report for the Burnett #2-1, please refer to Document #693902647. A construction crew was on-site during this inspection. Damp soil was evident along the eastern edge of the location as well as outside of the perimeter fencing.	hughesjo	09/02/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800979	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5522864