

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/31/2021

Submitted Date:

09/02/2021

Document Number:

696104963**FIELD INSPECTION FORM**Loc ID 414138 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 27742Name of Operator: EOG RESOURCES INCAddress: 600 17TH ST STE 1100NCity: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Limongelli, Kristen	(303) 501-2132	kristen_limongelli@eogresources.com	Regulatory Administrator
Morgan, John		john.morgan@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413064	WELL	AC	09/01/2011	OBW	123-30585	Bevo 4-36 SWD	PA

General Comment:

This is a PLUGGED & ABANDONED WELL / CEMENTING inspection.

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations / Cementing in progress. Initial plugs.

Battery: Abandoned. ALL Equipment removed.

Abandoned Battery SE corner GPS coordinates: 40.967955 / -104.384042

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐

Signs/Marker:			
Type			
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Wellhead: w/ Master and casing valves.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 413064 Type: WELL API Number: 123-30585 Status: AC Insp. Status: PA

CementCement ContractorContractor Name: IEC Services

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 8500' -8100'Cement Volume (sx): 60 sxsGood Return During Job: YESCement Type: Class GComment:

Workover Contractor: Peak Well Services Rig.
Cementing Contractor: IEC Services.

Reference:

Form 42 doc. #402790309. Notice of plugging start date: 08/30/2021. Approved.
Form 6 doc. #402675537. Notice of Intent to Abandon date: 07/28/2021. Approved.
Form 17 doc. #402778355. Bradenhead Test Report date: 08/10/2021. Approved.
Prior MIT. Form 21-MIT doc. #402293584. MIT date: 06/14/2018. Approved.
Site appears secure.

Initial plugs:

RIH w/CIBP, Run 269 jts, set @ 8500'. Fill casing & pressure test to 1016 psi.
Hold for 15 mins.
Pump 40 sxs Class G cement. POOH 9 jts Rev Circ w/ 31 Bbls. POOH. RIH w/ CIBP
and 256 jts. Set CIBP @ 8100. Break circ. Pump 20 sxs of Class G cement.
POOH 5 jts, Rev Circ, POOH w/ 228 jts. SWIFN.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 08/31/2021 at approximately 09:31 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: EOG RESOURCES INC Location Name: BEVO /4-36M Location ID: 414138 Well Name(s): Bevo 4-36 SWD. API: 05-123-30585. Location County: Weld County, Colorado Weather: Mostly Sunny w/ haze, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations / Cementing in progress. Initial plugs. Battery: Abandoned. ALL Equipment removed. Abandoned Battery SE corner GPS coordinates: 40.967955 / -104.384042</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Initial plugs & cement pumped. Form 6N doc. #402675537 indicates Notice of Intent to Abandon date: 07/28/2021. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/02/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104964	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5522983