

Inspection Photos
Location Name: Neleigh 01-07 #1
API: 05-067-06357



Neleigh 01-07 #1 location photo.



Neleigh 01-07 #1 well head and flow line.

Inspection Photos
Location Name: Neleigh 01-07 #1
API: 05-067-06357



Excavation around flow line at well head.



Excavation around flow line.

Inspection Photos
Location Name: Neleigh 01-07 #1
API: 05-067-06357



Flow line in open trench.



Flow line exposed up to separator.