

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2021

Submitted Date:

09/02/2021

Document Number:

688800982**FIELD INSPECTION FORM**Loc ID 325151 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|--------------|------------------------------|---------------------------------|
| Fischer, Alex | | alex.fischer@state.co.us | |
| Williford, Hearne | 918-712-8828 | hwilli@swbell.net | |
| Stevens, Glenn | 970-749-0192 | glennstevens@centurylink.net | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 214134 | WELL | SI | 02/01/2020 | OW | 067-05446 | DYE-HARD 1 | EI |

General Comment:

On August 26, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Dye Hard #1. For the most recent field inspection report of this facility, please refer to document #693903144.

| Location | | | | |
|--|--|--------|--|------------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | BATTERY | | | |
| Comment: | Free standing sign near AST at tank battery. | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | Free standing sign near pump jack. | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | Posted on location signs. | | | |
| Corrective Action: | | | | Date: _____ |
| Good Housekeeping: | | | | |
| Type | WEEDS | | | |
| Comment: | Weeds present throughout secondary containment berm. | | | |
| Corrective Action: | Comply with Rule 606. | | | Date: 09/09/2021 |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: _____ | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | PUMP JACK | | | |
| Comment: | Guard fencing present. | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| Type: Ancillary equipment | # 1 | | | corrective date |
| Comment: | Electrical supply equipment. | | | |
| Corrective Action: | | | | Date: |
| Type: Pump Jack | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Prime Mover | # 1 | | | |
| Comment: | Electric motor. | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS | |
|-----------|---|----------|-----------|---------|-----------------------|--|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 37.109263,-108.110056 | |

| | |
|----------|--|
| Comment: | |
|----------|--|

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|-------|----------|---------------------|---------------------|-------------|--|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Inadequate | |

| | |
|----------|--|
| Comment: | Weeds present throughout secondary containment berm. |
|----------|--|

| | | | |
|--------------------|-----------------------|-------|------------|
| Corrective Action: | Comply with Rule 606. | Date: | 09/09/2021 |
|--------------------|-----------------------|-------|------------|

Wells Served By Facilities Above

| |
|------------|
| API Number |
| 067-05446 |

AirsID

| | |
|------------|--------|
| API Number | AirsID |
|------------|--------|

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 214134 | Type: | WELL | API Number: | 067-05446 | Status: | SI | Insp. Status: | EI |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---|
| Compaction | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | Secondary containment for blow down drum. |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|----------|------------|
| On August 26, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Dye Hard #1. For the most recent field inspection report of this facility, please refer to document #693903144. Weeds present throughout secondary containment berm. | hughesjo | 09/02/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 688800983 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523228 |