

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: 4' barb wire with Wood poles

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment # 1

Comment: Electric equipment

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: Electric motor

Corrective Action:

Date:

Type: Bradenhead # 1

Comment: Plumbed to surface

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 249133 Type: WELL API Number: 123-16935 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/11/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were clear, smoggy, hot, small breeze.	medinaj	09/01/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503147	Inspection pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523265