

Inspection Photos (09-01-2021)
Location Name: Martin J Schaefer #2 Flowline
Spill/Release ID: 480698



Location sign



Absorbent booms deployed by the operator.

Inspection Photos (09-01-2021)
Location Name: Martin J Schaefer #2 Flowline
Spill/Release ID: 480698



Operator's personnel working along the unnamed ditch.



**Operator's personnel deploying absorbent pads in the ditch.
Note temporary dam behind the person.**

Inspection Photos (09-01-2021)
Location Name: Martin J Schaefer #2 Flowline
Spill/Release ID: 480698



Second temporary dam constructed to restrict water from entering wetland.



Operator's personnel deploying absorbent pads in the ditch.

Inspection Photos (09-01-2021)
Location Name: Martin J Schaefer #2 Flowline
Spill/Release ID: 480698



Partial view of the impacted reach of the ditch.



"Spent" absorbent booms.

Inspection Photos (09-01-2021)
Location Name: Martin J Schaefer #2 Flowline
Spill/Release ID: 480698



Oil (orange) floating on water in the ditch.



Small excavation in background filled with blue opaque water.

Inspection Photos (09-01-2021)
Location Name: Martin J Schaefer #2 Flowline
Spill/Release ID: 480698



Excavation opened to expose the release point.



Excavation opened to expose the release point.

Inspection Photos (09-01-2021)
Location Name: Martin J Schaefer #2 Flowline
Spill/Release ID: 480698



Orange safety fencing delineating the open excavation.



Orange safety fencing delineating the open excavation.

Inspection Photos (09-01-2021)
Location Name: Martin J Schaefer #2 Flowline
Spill/Release ID: 480698



Spoil pile on top of a liner.



Operator's personnel deploying silt fence as a storm water BMP.

Inspection Photos (09-01-2021)
Location Name: Martin J Schaefer #2 Flowline
Spill/Release ID: 480698



Silt fence being used as a storm water BMP.

