

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/31/2021

Submitted Date:

09/03/2021

Document Number:

697601510

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1675 BROADWAY, STE 2800
 City: DENVER State: CO Zip: 80202

Findings:
4 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, KPK		cogcc@kpk.com	All KPK Inspections
Knop, Max	303-825-4822	MKnop@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479834	SPILL OR RELEASE	CL	07/30/2021		-	Suckla Farms E #2 Flowline	EI

General Comment:

[Steel panel fencing in place surrounding excavation. No Operator staff present at time of inspection](#)

[Ongoing Remediation project 19028 at now closed spill 479834.](#)

[Sorbent booms observed in main excavation in effort to minimize horizontal transport of crude oil in precipitation event are not in place near hydrocarbon liquids at time of inspection. This inspection entered to document conditions observed at time of inspection. Operator has indicated they removed observed hydrocarbon liquids prior to this inspection being submitted.](#)

[No barrier to prevent infiltration of crude oil and associated impacts to deeper soils and to shallow groundwater at site during precipitation or irrigation events.](#)

[Weeds noted in previous two inspection \(07/21/2021 and 08/17/2021\) have been removed from excavation area.](#)

Inspected Facilities

Facility ID: 479834 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: OIL Estimated Spill Volume: _____

Comment: attached photo to document presence of free hydrocarbon liquids/product flating on water at bottom of excavation for spill 479834.

Corrective Action: remove free liquids/product within 24 hour of notice.Email notice sent on 08/31/21 and acknowledged by Operator staff on same day.email attached.Control and contain spills/releases and clean up per Rule 912.a. Date: 09/01/2021

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: Other Comment: bottom of excavation

Sample Sample Type: SOIL GRAB

Time: 08/31/2021 07:44 (MM/dd/yyyy hh:mm) GPS: Lat _____ Long _____

BTEX: _____ TPH: YES Anion: _____ Captions: _____ General Chemistry: _____

Dissolved Methane: _____ Composition: _____ Stable Isotopes: _____ 8260: _____

8270: _____ RCRA Metals: _____ 910-Metals: YES PAH: YES

Other: SIMPAH by 8270 and Table 915-1 metals by 6020

Comment: oily soil from bottom of excavation about 2 feet from liquid HC on water

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601511	free product on aqueous zone	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523891
697601512	email notice of required actions 08/31/21 and response	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523892