

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2021

Submitted Date:

09/03/2021

Document Number:

688800992**FIELD INSPECTION FORM**Loc ID 312051 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Rowley, Darren		drowley@logosresourcesllc.com	All inspections
		regulatory@logosresourcesllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216532	WELL	TA	05/01/2019	GW	067-08138	BONDAD 33-9 22A	EI
480361	SPILL OR RELEASE	AC	08/05/2021		-	SPILL/RELEASE POINT	EI

General Comment:

On August 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Logos Operating LLC Bondad 33-9 #22A. For the most recent field inspection report of this facility, please refer to document #693903486. This site visit was performed to follow up on Spill/Release Point ID #480361.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to separator.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		37.128938,-107.799315
Comment:	PBV information taken from previous inspection reports of this facility. PBV has been removed.				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	125 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Secondary containment information taken from previous inspection reports. Secondary containment has been removed.		
Corrective Action:		Date:	

Wells Served By Facilities Above**AirsID**

API Number	API Number	AirsID
067-08138		

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	216532	Type:	WELL	API Number:	067-08138	Status:	TA	Insp. Status:	EI
Facility ID:	480361	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 1

Comment: Please refer to Spill/Release Point ID #480361 for more information regarding this release. Operator reported spill as a precaution. Rule 912.b.(1) reporting thresholds were reportedly not met.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Per Rule 912.e.(1) the operator will submit a supplemental Form 19 to close Spill/Release Point ID #480361 with work proceeding under REM Project #19542.

Date: 10/01/2021

Reportable: NO

GPS: Lat 37.128935

Long -107.799304

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Spill/Remediation:

Comment: PBV and secondary containment berm have been removed as part of REM #19542.

Corrective Action: Provide a Supplemental Form 27 to update project file with analytical results and work conducted.

Date: 10/01/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On August 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Logos Operating LLC Bondad 33-9 #22A. For the most recent field inspection report of this facility, please refer to document #693903486. This site visit was performed to follow up on Spill/Release Point ID #480361. The 125 bbl. PBV has been removed from the location as part of REM #19542. The operator will provide an update of work completed to date and provide analytical results upon receipt. The operator will submit a Supplemental Form 19 to close Spill/Release Point ID #480361 with work proceeding under REM Project #19542.	hughesjo	09/03/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800993	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5524207